



March 3, 2016



Exposed

Looking through removed burner cans





Exposed



LEC





~\$7,000,000

~\$500,000

March 3, 2016



Problem Areas

Significant problem with broken bolts







Problem Areas

Row 2 nozzles, black circles are cracks





Problem Areas

Row 1 shroud block erosion





Costs

	Budgeted Cost	Projected Cost
Base Cost	\$308,368	\$308,368
Refurbishment	\$84,491	\$90,991
Parts	\$18,608	\$18,608
Contingency	\$88,533	\$36,154
	\$500,000	\$454,121

Remainder \$45,879