

Combustion Turbine

CT2 – STIG

Spring Maintenance

January 13, 2017



Re-assembly

Refurbished parts reinstalled on engine



January 13, 2017

Exposed

Combustion Cans



Problem Areas

- Evap Cooler Media Replaced



Problem Areas

- Evap Cooler Media Replaced



Costs

Projected Final Costs, Invoices not Received

- Outage is small
- Minor Repairs
- Mostly Calibrations and Filter Changes w/
NCPA Staff
- Control System Tests/Checks
- Fire System Tests
- Relief Valve Checks
- Switchgear Service
- ~\$25,000