

2017 GEOTHERMAL Winter Storm Damage



January 31, 2017

Mud seeping through conduits and into steam line insulation on H site road



January 31, 2017

H site road



January 31, 2017

P site road Jan 10th damage



January 31, 2017

Broken asphalt on P site road



Broken asphalt and sluffed off bank on P road



January 31, 2017

P site road stabilized



January 31, 2017

P Road Repair



P Road Repair




Estimated Repair Costs

H-Site	3,000	Excavator
	6,000	Dump Trucks
	<u> </u>	
	\$9,000	

P-Site	3,200	Dump Trucks
	12,300	Rip Rock (Boulders)
	<u> </u>	
	\$15,500	

Total repair estimated cost \$24,500
All in house labor

2017 GEOTHERMAL Winter Storm Damage



January 31, 2017